

GDR...- 4-5P Svorková spojka 100-2500 A

Overview:

Použitie

Služi na spájanie všetkých dielov.

- verzie pre 100 až 2500 A
- v 4 a 5 pólovom prevedení
- spájanie jednou skrutkou



A	GDR 4	GDR 5
	Symbol Type	Symbol Type
100/250	GDR7514	GDR6102
400/1600	GDR6014	GDR6135
1250/2500	GDR4G16	GDR5G16

Versions:

Symbol	Pól	El. prúd [A]
GDR7514	4P	100
GDR5G02	5P	100
GDR6014	4P	400
GDR6135	5P	400
GDR6015	4P	1250
GDR6136	5P	1250
GDR4G16	4P	2000
GDR5G16	5P	2000