

GDR...- 4-5P Svorková spojka 100-2500 A

Informácie:

Použitie

Slúži na spájanie všetkých dielov.

- verzie pre 100 až 2500 A
- v 4 a 5 pólovom prevedení
- spájanie jednou skrutkou



A	GDR 4		GDR 5	
	Symbol	Typ	Symbol	Typ
100/250	GDR7514	GDR6014	GDR6135	GDR6136
400/600	GDR6014	GDR6135	GDR6136	GDR6136
1250/2000	GDR6015	GDR6136	GDR6136	GDR6136
2000/2500	GDR4G16	GDR5G16	GDR5G16	GDR5G16

Verzie:

Symbol	Pól	El. prúd [A]
GDR7514	4P	100
GDR5G02	5P	100
GDR6014	4P	400
GDR6135	5P	400
GDR6015	4P	1250
GDR6136	5P	1250
GDR4G16	4P	2000
GDR5G16	5P	2000